
Item	Qty.	Description
1	4	38" GS220 Corner Extrusion
2,2A	1,1	57.381" Z45 Curved Horizontal Extrusion
3,3A	1,1	68.449" Z45 Curved Horizontal Extrusion
4,4A	2,2	13.5" Z45 Horizontal Extrusion
5	1	34.418" Z45 Vertical Extrusion
6	1	34.418" Z45 Vertical Extrusion


Steps:


- 1) Attach lower extrusions [2] [3] and [4] between verticals [1].
- 2) Attach verticals [5] and [6] to lower extrusion [2], with door between.
- 3) Insert infills between verticals [1] [5] and [6], making sure Velcro is facing inward.
- 4) Connect door to vertical [6]. See Door Connection detail.
- 5) Attach upper extrusions [2A] [3A] and [4A] between verticals [1], to secure infills.
- 6) Attach shelf supports to Velcro on inside of assembled counter then place shelf on top of supports.
- 8) Place counter top on assembled counter base. See Counter Top Lock detail.





Completed Counter Assembly













General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all set screws and locks during disassembly




Hex Tool - Essential for Assembly




Part Identification - Numbering



MARNING



Spline Connection




Base Plate & Extrusion Connection




DO NOT USE POWER TOOLS



LADDERS OR LIFTS MAY BE REQUIRED



Extrusion & Lock Connection



Engaged Lock



ALL CONNECTIONS MUST BE TIGHTLY SECURED