
	© 20
visiahəyu [*]	<u> </u>
DESIGNS	


Item 1 2 3 4 5 6,6A 7	Qty. 1 1 1 1 2 1,1 2	Description 38" GS220 Extrusion w/ 34.417" L-Channel 38" GS220 Extrusion w/ Door Hinges 38" GS220 Extrusion 38" GS220 Extrusion 38.026" Z45 Curved Extrusion 74.815" Z45 Curved Extrusion 24.813" Z45 Extrusion
8	2	24.813" Z45 Extrusion

Steps:

- 1) Attach lower extrusions [5] [6] and [7] between vertical extrusions [1] [2] [3] and [4].
- 2) Slide infills between [1] [2] [3] and [4], making sure Velcro is facing inward.
- 3) Secure infills with upper extrusions [5] [6A] and [8].
- 4) Attach door to vertical [2]. See Door Connection detail.
- 5) Connect shelf supports to Velcro on infills.
- 6) Place shelf on top of supports.
- 7) Lock counter top to extrusions [6A] and [8]. See Counter Top Lock detail.





Completed Front View





Completed Back View

Keep L-channel attached to extrusion [1].













General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering



MARNING



Spline Connection




Base Plate & Extrusion Connection




DO NOT USE POWER TOOLS



LADDERS OR LIFTS MAY BE REQUIRED



Extrusion & Lock Connection



Engaged Lock



ALL CONNECTIONS MUST BE TIGHTLY SECURED